



FIG. 3

8	7	9	5	4	3	2	1	
		~	<i>feasurement</i>	Measurement Results 2 IEI	EI			octet 1
		Serving c	ell and othe	Serving cell and other measurement results	ent results			Octet 2
			(Not re	(Not relevant)				Octet 3
								Octet 4
IND=1			RXLEV-NCELL	NCELL 1			IND=1	Octet 5
		RXLEV-1	RXLEV-NCELL 2			IND=1	RXLEV-	Octet 6
-		(low	(low part)				NCELL 3 (high part)	
	RXI	RXLEV-NCELL 3	L 3		IND=1	RXLEV.	RXLEV-NCELL 4	Octet 7
·		(low part)				(higl	(high part)	
- -	RXLEV-NCELL 4	VCELL 4		IND=1	ß	RXLEV-NCELL 5	LL 5	Octet 8
	(low part)	part)				(high part)		
RXLEV-h	RXLEV-NCELL 5 (low part)	ow part)	IND=0	IND=0	IND=0	IND=0	0=QNI	Octet 9
IND=0	IND=0	IND=0	0=QNI	0=QNI	IND=0	IND=0	IND=0	Octet 10
IND=0	IND=0	IND=0	IND=0	IND=0	IND=1	RXLEV-	RXLEV-NCELL24	Octet 11
	·					(higl	(high part)	
RXI	EV-NCEL	RXLEV-NCELL24 (low part)	art)	IND=1	RXLEV-	RXLEV-NCELL 25 (high part)	(high part)	Octet 12
RXLEV-N	RXLEV-NCELL 25 (low part)	low part)	IND=1	RX	LEV-NCEL	RXLEV-NCELL 26 (high part)	part)	Octet 13
RXLEV-NCELL 26	CELL 26	IND=1		RX	RXLEV-NCELL 27	L 27		Octet 14
(low part)	art)				(high part)			
RXLEV-	IND			RXLEV-	RXLEV-NCELL 28			Octet 15
NCELL	ī							
27						-		
(low part)								
IND=1			RXLEV-1	RXLEV-NCELL 29			IND=0	Octet 16
IND=0	IND=1			RXLEV-	RXLEV-NCELL 32	: 4		Octet 17
		-						

FIG. 4